



Bid Notice Abstract

Request for Quotation (RFQ)

Reference Number 11358744
Procuring Entity NATIONAL IRRIGATION ADMINISTRATION - ZAMBOANGA SIBUGAY
Title Supply of Parts & Labor for Repair & Maintenance of Isuzu Fuego I1-1757 and Tamaraw FX I1-1688
Area of Delivery Zamboanga Sibugay

Solicitation Number:	Supply of Parts & Labor for Repair & Maintenance	Status	Active
Trade Agreement:	Implementing Rules and Regulations	Associated Components	1
Procurement Mode:	Negotiated Procurement - Small Value Procurement (Sec. 53.9)	Bid Supplements	0
Classification:	Goods - General Support Services	Document Request List	0
Category:	Vehicle Repair and Maintenance	Date Published	15/10/2024
Approved Budget for the Contract:	PHP 72,050.00	Last Updated / Time	15/10/2024 00:00 AM
Delivery Period:	30 Day/s	Closing Date / Time	21/10/2024 09:00 AM
Client Agency:			
Contact Person:	MARIA GERTRUDES PAGUTE GANIA BAC Chairperson/Sr. Engineer A DA-RFOIX Research Division Compound, Sanito, Ipil Zamboanga Sibugay Philippines 7001 63-948-8713237 niazambosibugaysvisimo@yahoo.com		

Description

NO. QTY UNIT AGENCY'S SPECIFICATION

Supply of Parts & Labor for Repair & Maintenance of Isuzu Fuego I1-1757 and Tamaraw FX I1-1688

Isuzu Fuego I1-1757

1 2 pc Lower Ball Joint

2 2 pc Upper Ball Joint

3 2 pc Wheel Brake Cylinder

4 2 pc Front Shock Absorber

5 2 pc Rear Shock Absorber

6 1 pc Caliper Bolt

7 1 pc Tie Rod End

8 1 pc Cross Joint

9 5 ltr Engine Oil 15w-40

10 1 pc Oil Filter C-512

11 1 pc Fuel Filter FC-208A

12 2 pc Bulb 12V

13 1 pc Electrical Tape

14 1 pc Gas Tank Cap

15 1 lot Labor: Welding Repair of Chasis; Replace Rer Cab Body Support; Change Engine Oil, Oil Filter & Fuel Filter; Pull-out & Repair Clutch Pedal; Repair Hood Hinge Bracket; Machine Shop Idler Arm Bushing; Replace Upper & Lower Ball Joint; Replace Idler Arm; Replace Tie Rod End; Replace Rear & Front Shock Absorber; Replace Cross Joint; Replace Wheel Brake Cyliner Left & Right; Wiring of Signal Light & Hazard Light

Tamaraw FX I1-1688

16 2 pc Axle Bearing

17 2 pc Stabilizer Kit

18 4 pc Rubber Cap 19 2 pc Axle Oil Seal 20 2 pc Axle Bearing Lock 21 4 ltr Engine Oil 15w-40 22 1 pc Oil filter C-112 23 1 lot Labor: Replace Brake Rubber Cap Left & Right; Pull-out of Axle and Press of Bearing Left & Right; Replace Stabilizer Kit Left & Right; Change Oil Engine x-x-x-x(Nothing Follows)x-x-x-x

Created by MARIA GERTRUDES PAGUTE GANIA

Date Created 14/10/2024

The PhilGEPS team is not responsible for any typographical errors or misinformation presented in the system. PhilGEPS only displays information provided for by its clients, and any queries regarding the postings should be directed to the contact person/s of the concerned party.

© 2004-2024 DBM Procurement Service. All rights reserved.

[Help](#) | [Contact Us](#) | [Sitemap](#)